










A (mm)	B (mm)	C (mm)	D (mm)
640	1149	1937	1939-1942




A


1




2







3





4






B




2



3




A 4x I 1x




3.1

1x1




3.2

Ax4




3.3




4


C 2x




4.1



4.2



4.3



5

(A) 4x

5.1

0 mm

41,0 mm



5.2



Ax3

1x

5.3

Ax3

Rx2




6

(H) 4x


(B) 4x

(D) 1x

6.1



6.2



6.3

Bx4

(B)



7 **E** 4x **A** 4x

7.1

7.2

4x

Ax4

min 90

J

K

M

L

8 **3x**

8.1 **8.2** **8.3**

9 **B** 4x

9.1

9.2

4x

B


10 **A** 8x

8x

Ax8


11

F 4x B 8x




11.2

8x



11.3



b

